

Inspection Photos
Operator: Catamount Energy
API: 007-06098
Date: 9/11/2020



Photo 1. View of the project area from the northwestern corner facing center toward the well.



Photo 2. View of wattles placed on the northwestern cut-slope. Some wattles appear to be functioning; however, many are out of place.



Photo 3. View of wattle in the southwestern project area that is full of sediment.



Photo 4. Downstream facing view of erosional channel identified during 2019 reclamation inspection. Wattles are installed, but out of place, full of sediment, and largely, not longer functioning. Wattles are not an adequate BMP in this area.



Photo 5. View of fencing and barbed wire debris.



Photo 6. View of the southern project area from the southwestern corner facing eastward.



Photo 8. View of reference area vegetation comprised of ponderosa pine forest with gambel oak, snow berry, Oregon grape, and junegrass in the understory.