

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/08/2020

Submitted Date:

09/16/2020

Document Number:

688308512

FIELD INSPECTION FORMLoc ID 316997 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10691

Name of Operator: PHOENIX RESOURCES LLC

Address: 5566 S SYCAMORE STREET

City: LITTLETON State: CO Zip: 80120

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Heffner, Taylor	303-219-3362	theffner@phxresources.com	
Wolfe, Stephen		stephen.wolfe@state.co.us	COGCC Engineer

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
234270	WELL	SI	10/01/2018	OW	121-06377	BLAKE 1	TA

General Comment:

MIT Inspection, FAILED

Form 42 Notice 402478153

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
Crude Oil	WELLHEAD	<= 1 bbl		
Comment: Crude oil at wellhead spilled while pressuring well up, ~10 gals. Was contained in dirt berm right away.				
Corrective Action: Properly dispose of stained soil			Date:	09/16/2020

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 234270 Type: WELL API Number: 121-06377 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: MIT, FAILED, hole failed to load or hold to pressure, pressured up to 370 psi but went to below 300 psi in a minute, bradenhead leaking oilCorrective Action: **Repair (retest) or plug and abandon.**Date: 12/08/2020**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688308519	Phoenix Resources Blake 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5248902
688308533	Form 21 Failed	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5248903