

Construction and Stormwater Inspection

September 15, 2020

Operator: NOBLE ENERGY INC- #100322

Location ID: 459435

Inspection Document #: 697501997

Weld County, CO

NWSW Section 5 T3N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources



Photo 1. Photo taken from the northern location, facing South. Photo illustrates Operator is in process of performing topsoil salvage operations.

Inspection Photos
Location Name: D05-12 /Multi
Location ID: 459435



Photo 2. Photo taken from the northeastern location, facing West. Photo illustrates Operator has installed stormwater BMPs (ditch and berm, filtrex wattles) around the entire perimeter of location.

Inspection Photos
Location Name: D05-12 /Multi
Location ID: 459435



Photo 3. Photo taken from the northeastern location, facing East. Photo illustrates Operator is stockpiling topsoil along the northeastern location.

Inspection Photos
Location Name: D05-12 /Multi
Location ID: 459435



Photo 4. Photo taken from the northern section of the location, facing South. Photo illustrates Operator appears to be salvaging topsoil to an appropriate depth.

Inspection Photos
Location Name: D05-12 /Multi
Location ID: 459435



Photo 5. Photo taken from the northwestern location, facing South. See comments under Photo 2.

Inspection Photos
Location Name: D05-12 /Multi
Location ID: 459435



Photo 6. Photo taken from the southeastern location, facing East. See comments under Photo 2.

Inspection Photos
Location Name: D05-12 /Multi
Location ID: 459435



Photo 7. Photo taken from the southeastern location, facing North. See comments under Photo 2.

Inspection Photos
Location Name: D05-12 /Multi
Location ID: 459435



Photo 8. Photo taken from a portion of the main access road, facing North. Photo illustrates Operator had a water truck on location controlling fugitive dust.