

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/16/2020

Submitted Date:

09/16/2020

Document Number:

699801794

FIELD INSPECTION FORM
 Loc ID 312498 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

3 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Graves, Jim		mrinc20@maralexinc.com	
Jordan, Reid		maralextechjr@gmail.com	
, Engineering		dnr_cogccengineering@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221784	WELL	SI	01/08/1992	GW	077-08386	DOMA ALBERTSON 1-32	TA

General Comment:**COGCC Inspection Report Summary**

On Wednesday 9/16/20 at approximately 14:00 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at MARALEX RESOURCES INC DOMA ALBERTSON-69S98W /32SENW, Location #312498 in Mesa County Colorado.

Refer to document #699801006 inspection conducted on 4/29/20. Not all previous corrective actions have been completed.

During this inspection the following possible compliance issues were observed: Multiple places with debris on location. See photo #1090, #1893, #1091 and #1894 with a previous corrective action date of 5/13/20. MIT required on well. With a previous corrective action date of 7/29/20. No pit permit on record. With a previous corrective action date of 5/29/20.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L		Date:	
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:			Date:	
Emergency Contact Number:				
Comment:	911			
Corrective Action:			Date:	
Good Housekeeping:				
Type	DEBRIS			
Comment:	Multiple places with debris on location. See photo #1090, #1894 ,#1091 and #			
Corrective Action:	Production facilities, shall be kept free of weeds and rubbish. Remove all debris from location.		Date:	05/13/2020
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PIT			
Comment:	Hog panels			
Corrective Action:			Date:	
Equipment:				
Type: Plunger Lift	# 1			corrective date
Comment:				
Corrective Action:			Date:	
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:			Date:	
Flaring:				
Type				
Comment:				
Corrective Action:			Date:	



Inspected FacilitiesFacility ID: 221784 Type: WELL API Number: 077-08386 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: Last produced prior to 1999. Last MIT preformed on 1/28/14.Corrective Action: A mechanical integrity test shall be performed on each shut-in well on 5 year intervals from the date the initial mechanical integrity test was performed. Preform MIT on well.Date: 07/29/2020

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: BlowdownLined: NO

Pit ID:

Lat:

Long:

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type:

Liner Condition:

Comment: No pit permit on record.

Corrective Action

Submit an eForm 15 Pit Report to update COGCC records with current information.Date: 05/29/2020**Fencing:**Fencing Type: LivestockFencing Condition: Adequate

Comment:

Corrective Action

Date:

Netting:

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present: NOOil Accumulation: NO2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

COGCC Comments

Comment	User	Date
<u>All equipment has been removed from location. All that remains is the wellhead and pit.</u>	depaoloc	09/16/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699801795	Photos for Insp. #699801794	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5249644