

Construction and Stormwater Inspection

September 15, 2020

Operator: NOBLE ENERGY INC- #100322

Location ID: 459443

Inspection Document #: 697501999

Weld County, CO

NWSE Section 5 T3N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: D05-10 /Pad
Location ID: 459443



Photo 1. Photo taken from the entrance of location, facing Southeast. Photo illustrates Operator permits per the Form 2A COA.

Inspection Photos
Location Name: D05-10 /Pad
Location ID: 459443



Photo 2. Photo taken from the northwestern location, facing East. Photo illustrates one of two topsoil stockpiles. Most of the stockpile has been temporarily stabilized with equipment tracking and planned operations will be performed for long-term stabilization.



Photo 3. Photo taken from the northern location, facing East. Photo illustrates Operator has installed stormwater BMPs (ditch and berm, filtrex wattles) around the entire perimeter of location. Note: north-facing stockpile has not been stabilized. Operator indicated this would be stabilized with hydromulch and broadcast seeding.

Inspection Photos
Location Name: D05-10 /Pad
Location ID: 459443



Photo 4. Photo taken from the northeastern location, facing South. See comments under Photo 3.

Inspection Photos
Location Name: D05-10 /Pad
Location ID: 459443



Photo 5. Photo taken from the southeastern location, facing West. See comments under Photo 3.

Inspection Photos
Location Name: D05-10 /Pad
Location ID: 459443



Photo 6. Photo taken from the southwestern location, facing East. Photo illustrates the second topsoil stockpile which has been temporarily stabilized with equipment tracking.

Inspection Photos
Location Name: D05-10 /Pad
Location ID: 459443



Photo 6. Photo taken from the southwestern location, facing North. Photo illustrates the cut slope has been temporarily stabilized with equipment tracking.

Inspection Photos
Location Name: D05-10 /Pad
Location ID: 459443



Photo 7. Photo taken from the southwestern location, facing Northeast. Photo illustrates Operator is in process of added roadbase to the location.

Inspection Photos
Location Name: D05-10 /Pad
Location ID: 459443



Photo 8. Photo taken from a portion of the main access road, facing North. Photo illustrates Operator had a water truck on location controlling fugitive dust.