

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/12/2020

Submitted Date:

09/14/2020

Document Number:

700600143

FIELD INSPECTION FORM

Loc ID 308023 Inspector Name: Kosola, Jason On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD State: CO Zip: 8111-

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Santistevan, Vince	719-845-2102/719-680-9705	vincesantistevan@tcenergyllc.com	All Inspections
Mack, Ronald		ronaldmack@tcenergyllc.com	All Inspections
Fitzgerald, Edie	719-859-1394	ediefitzgerald@tcenergyllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260235	WELL	PR	08/04/2011	GW	071-07405	APACHE CANYON 18-04V	EI

General Comment:

This inspection is being entered for notification and documentation only and is not intended to provide the Operator the opportunity to resolve the alleged violations without the imposition of a penalty, pursuant to Rule 522.c.

Reports indicated that this location may have been a dump site for oily waste. Report indicated that the liquid ring on location was moved on top of dump site. Multiple holes were drilled with a hand auger to obtain soil borings from 2 spots under the liquid ring (see attached photos) and 3 other locations on well pad. No oily waste was found in soil borings. COGCC Inspection from 2018 shows liquid ring is in same location. It is unclear from reports of illegal dumping when this is alleged to have occurred. This inspector found no evidence of buried oily waste at the time of this inspection.

Stormwater channel of south side of location should be addressed. See corrective action.

Thief hatch on tank was open during inspection. Thief hatches should remain closed at all times.

Inspected Facilities

Facility ID: 260235 Type: WELL API Number: 071-07405 Status: PR Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Multiple areas of erosion from lack of stormwater BMPs. See attached photos of erosion from water coming onto and off of well pad.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.\(2\)C](#)

Date: 09/30/2020

Pits: NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	268873	1121972	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700600144	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5249901