

Inspection Photos
Operator: BP America
API: 067-09066
Date: 9/15/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern fill slope from the southwestern corner facing eastward. Revegetation is progressing within the interim reclamation area, largely with grasses such as western wheatgrass and sand dropseed.



Photo 3. View of reference area vegetation comprised of ponderosa pine woodland with understory of gambel oak, snowberry, black sage, and western wheatgrass.



Photos 4/5. Locked gate coming in (left) and leaving (right).