

Inspection Photos
Operator: BP America
API: 067-07752
Date: 9/15/2020



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western cut-slope from the southern corner facing northwestward. Revegetation is progressing within the interim reclamation area, largely with grasses such as western wheatgrass, smooth brome, and sand dropseed. Stormwater BMPs are largely functioning, but maintenance is needed. Portions of revegetation on the northeastern cut-slope remain sparse and need to be monitored and re-seeded if not increasing.



Photo 3. View of BMPs on the northwestern edge of the project area, needing maintenance.



Photo 4. View of reference area vegetation comprised of pinyon and juniper woodland with shrubs and forbs in the understory such as big sagebrush, gambel oak, buckwheat, and Indian ricegrass.



Photos 6/75. Locked gate coming in (left) and leaving (right).