

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/17/2020

Submitted Date:

09/17/2020

Document Number:

694400341

FIELD INSPECTION FORM

Loc ID 435381 Inspector Name: Kraich, Adam On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10071
Name of Operator: HIGHPOINT OPERATING CORPORATION
Address: 555 17TH ST STE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
Barber, Matt		mbarber@hpres.com	All Inspections
Singer, Sheila		ssinger@hpres.com	All Inspections
Watt, Dustin		dwatt@hpres.com	Sr. EHS Specialist

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435381	LOCATION	AC	12/11/2013		-	Bronco Compressor Station 6-62-23	AC

General Comment:

Inspected Facilities

Facility ID: 435381 Type: LOCATION API Number: - Status: AC Insp. Status: AC

Producing Well

Comment: AC

Inspection in response to fire on location.
COGCC Staff arrived on location 9/17/2020 @ 11:39am.
Fire extinguished upon OGCC arrival, FD departed location.
Housed compressor unit appears to be damaged.
No PFAS foam used in fire fighting efforts, all water was contained on location.
No photos will be attached to this inspection report as investigation into causation is ongoing.

END OF REPORT.

Corrective Action:

Date: