

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/15/2020

Submitted Date:

09/16/2020

Document Number:

688308530**FIELD INSPECTION FORM**Loc ID 467075 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 35080Name of Operator: GRAND MESA OPERATING COAddress: 1700 N. WATERFRONT PKWY BL 600City: WICHITA State: KS Zip: 67206**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|----------------|--------------------|------------------|
| Reilly, Michael | (316) 265-3000 | mreilly@gmocks.com | Principal Agent |
| Reilly, Pat | 316-265-3000 | preilly@gmocks.com | Designated Agent |
| Brewer, Phyllis | (316) 265-3000 | pbrewer@gmocks.com | Designated Agent |
| Hutton, Neil | | nhutton@gmocks.com | Designated Anent |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 467074 | WELL | DG | 02/25/2020 | | 073-06770 | DADO 2-21 | WO |

General Comment:

Frac Inspection

LocationOverall Good: ☐**Signs/Marker:**

| | | | |
|--------------------|-----------------|-------|--|
| Type | DRILLING/RECOMP | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | |
|--------------------|--|-------------|
| Comment: | | Date: _____ |
| Corrective Action: | | |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected FacilitiesFacility ID: 467074 Type: WELL API Number: 073-06770 Status: DG Insp. Status: WO**Well Stimulation**Stimulation Company: Gore NitrogenStimulation Type: OTHER**Observation:**Other: slick waterMaximum Casing Recorded: 4884 PSI

Tubing: _____

Surface: _____

Intermediate: _____

Production: _____

Instantaneous Shut-In Pressure (ISIP) 4673Bradenhead Psi: 0

Frac Flow Back: _____

Fluid: _____

Gas: _____

Comment: Peak Wireline perfd @ 8185-8192'Stage 1 of 24 pumps5K wellhead7K casingCBL Submitted?

Corrective Action: _____

Date: _____

WorkoverComment: Codel Rig #5

Corrective Action: _____

Date: _____

Completion

Operation: _____

Date Flowback: _____

Contractor: _____

Comment: _____

Corrective Action: _____

Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 688308534 | Grand Mesa Dado 2-21 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5250312 |