

**Inspection Photos**  
**Operator: BP America**  
**API: 067-09062**  
**Date: 9/15/2020**



Photo 1. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing with western wheatgrass.



Photo 2. View of erosional channel (approx. 1 ft wide and 6-8 in deep) in the southeastern project area and wattle needing repair /maintenance.



Photo 3. View of bare soils on the northern cut-slope. Erosion controls are needed here.



Photo 4. View of reference area vegetation comprised of pinyon and juniper woodland with shrubs and forbs in the understory such as big sagebrush, gambel oak, buckwheat, and Indian ricegrass.



Photos 5/6. Locked gate coming in (left) and leaving (right).