

Inspection Photos
Operator: BP America
API: 067-09064
Date: 9/15/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing with grasses and shrubs such as western wheatgrass and rubber rabbitbrush.



Photo 3. View of the eastern project area from the northeastern corner facing southward.



Photo 4. View of reference area vegetation comprised of pinyon and juniper woodland with shrubs and forbs in the understory such as big sagebrush, gambel oak, buckwheat, and Indian ricegrass.



Photos 5/6. Locked gate coming in (left) and leaving (right).