

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: Red AG fencing

Corrective Action:

Date: _____

Equipment:

corrective date

Type: Plunger Lift # 2

Comment:

Corrective Action:

Date: _____

Type: Ancillary equipment # 1

Comment: electric / automation

Corrective Action:

Date: _____

Type: Prime Mover # 1

Comment: electric motor

Corrective Action:

Date: _____

Type: Pump Jack # 1

Comment:

Corrective Action:

Date: _____

Type: Bradenhead # 3

Comment:

Corrective Action:

Date: _____

Venting:

Yes/No NO

Comment:

Corrective Action:

Date: _____

Flaring:

Type

Comment:

Corrective Action:

Date: _____

Inspected Facilities

Facility ID: 433782 Type: WELL API Number: 123-37773 Status: PR Insp. Status: PR

Facility ID: 433784 Type: WELL API Number: 123-37774 Status: SI Insp. Status: SI

Facility ID: 433809 Type: WELL API Number: 123-37791 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection weather conditions were sunny and calm.	medinaj	09/15/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699501707	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5250427