

Inspection Photos

API: 071-08063

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 9/11/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08063 | Date: 9/11/2020

Inspection Photos



Photo 1. Facing north along the main access road. The culvert is filled in with sediment. Lat/Long:37.15037,-104.88728.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08063 | Date: 9/11/2020

Inspection Photos



Photo 2. Stormwater is not properly diverted toward the culvert.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08063 | Date: 9/11/2020

Inspection Photos



Photo 3. There is erosion along the side of the road that needs to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08063 | Date: 9/11/2020

Inspection Photos



Photo 4. There is erosion along the side of the road that needs to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08063 | Date: 9/11/2020

Inspection Photos



Photo 5. Facing south toward the location.

