

Inspection Photos

9/17/2020

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 335921

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 1: Photo shows signage has been installed/updated at well.



Photo 2: Photo shows signage has been installed/updated at well.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 3: Photo shows unused ladder equipment has been removed, and panels/fence has been maintained.



Photo 4: Photo taken from the southeast end of the Location, facing east. Photo shows areas of the Location, including fill slopes, that have not been recontoured/regraded or reclaimed to their original condition in accordance w/ 1003 rules. BMPs appear insufficient or missing to stabilize slopes.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 335921



Photo 5: Photo taken from the southeast end of the Location, facing west. Photo shows areas of the Location, including fill slopes, that have not been recontoured/regraded or reclaimed to their original condition in accordance w/ 1003 rules. BMPs appear insufficient or missing to stabilize slopes. .



Photo 6: Photo taken from the south of the Location, facing north. Photo shows fill slopes that have not been recontoured/regraded or reclaimed to their original condition in accordance w/ 1003 rules.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 7: Photo taken from the east end of the Location, facing south. Photos 7-8 provide an overview of the Location from south to southwest. Photo also shows areas (left of arrow) that appear to be subsoils; it does not appear that topsoil horizons were placed back to their relative original position.



Photo 8: See comments under photo 7

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 8.1 Photo copied from the 8/4/2020 inspection, taken from the northeast end of the Location, facing south. Photo shows interim areas. Soils at the surface appear to be subsoils; it does not appear that topsoil horizons were placed back to their relative original position.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 8.2 : Continued from photo 8.1 Photo show soil surface of interim area. it does not appear that topsoil horizons were placed back to their relative original position.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 335921



Photo 9: Photo taken from the east end of the Location, facing southwest. Photo shows cut slopes; interim areas have not been contoured/regraded and reclaimed to their original condition.



Photo 10: Photo of cut slopes on the north end of the location, facing north. Photo shows BMPs remain missing or insufficient to stabilize slopes.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 11: Photo taken from the southwest end of the Location, facing west. Photo shows erosion net BMP remains in disrepair, and is considered Debris.



Photo 12: Continued from photo 11. Photo shows erosion net BMP remains in disrepair, and is considered Debris.