

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/16/2020

Submitted Date:

09/17/2020

Document Number:

696103741

FIELD INSPECTION FORM

Loc ID 306455 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

11 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288951	WELL	SI	01/01/2018	GW	123-24696	ROUSE-USX A 5-17	SI

General Comment:

This is a WELL inspection.
Well(s): 1: Shut-In | SI.
Battery: Inactive | Shut-down.

Centralized Battery serves 9 Location IDs (302629, 302678, 302694, 306453, 302618, 302695, 302581, 302582, 306455).
(Well(s): 9: Shut-In | SI).

Refer to Field Inspection Report doc. #696103727 and/or Location ID #302629 for Battery / Facility, Equipment info.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type			
Comment:	Refer to Field Inspection Report doc. #696103727 and/or Location ID #302629 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type			
Comment:	Refer to Field Inspection Report doc. #696103727 and/or Location ID #302629 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	
Equipment:			
Type: Bradenhead	# 1		corrective date
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type:	#		
Comment:	Refer to Field Inspection Report doc. #696103727 and/or Location ID #302629 for Battery / Facility, Equipment info.		

Corrective Action:					Date:	
Tanks and Berms:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		40.522864,-104.564086	
Comment:		Centralized Battery serves 9 Location IDs (302629, 302678, 302694, 306453, 302618, 302695, 302581, 302582, 306455). Refer to Field Inspection Report doc. #696103727 and/or Location ID #302629 for Battery / Facility, Equipment info.				
Corrective Action:					Date:	
Paint						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities

Facility ID: 288951 Type: WELL API Number: 123-24696 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Shut-In | SI.
Locked-Out, Tagged-Out | LOTO.
COGCC records indicate last production: 08/2016.
SI/TA well per Alternative Mechanical Integrity Assurance Program
(Alternative Program). Doc #02385001 (NOBLE).

Corrective Action:

Date:

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary: On WED 09/16/2020 at approximately 13:09 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: ROUSE-USX A-66N64W /5SENE Location ID: 306455 Well Name: Rouse USX-A 5-17 API: 05-123-24696 Location County: Weld County, Colorado Weather: Mostly clear w/ haze, dry.</p> <p>While there, I observed: Well(s): 1: Shut-In SI. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 9 Location IDs (302629, 302678, 302694, 306453, 302618, 302695, 302581, 302582, 306455). (Well(s): 9: Shut-In SI).</p> <p>Refer to Field Inspection Report doc. #696103727 and/or Location ID #302629 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	09/17/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696103742	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5250566