

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/31/2020

Submitted Date:

09/01/2020

Document Number:

696201675

FIELD INSPECTION FORM

 Loc ID 324491 Inspector Name: Trujillo, Aaron On-Site Inspection 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 4 Number of Comments
 1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Operator Information:
 OGCC Operator Number: 77330
 Name of Operator: SG INTERESTS I LTD
 Address: 100 WAUGH DR SUITE 400
 City: HOUSTON State: TX Zip: 77007
Contact Information:

Contact Name	Phone	Email	Comment
,	970-385-0696	inspection@sginterests.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
324491	LOCATION	AC			-	Federal 11-90-15 1	RI
436817	WELL	PR	10/28/2017	GW	051-06129	Federal 11-90-15 3	PR

General Comment:

On 8/31/2020, Reclamation Specialist Trujillo conducted an interim reclamation and stormwater inspection at SG Interests' Federal 11-90-15 1 location in Gunnison County, Colorado.

This inspection is a followup to inspection #696201325, to document compliance with the following corrective actions:
 1002.f: Chemicals within containment
 1200: Protection of Wildlife Resources

Refer to the "Related Facilities" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Inspected Facilities

Facility ID: 324491 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Facility ID: 436817 Type: WELL API Number: 051-06129 Status: PR Insp. Status: PR

Producing Well

Comment: Inspection #696201325 observed that no BMPs have been implemented to prevent wildlife access at well head cellar.

It was observed in this inspection that BMPs to prevent wildlife access have not been installed at the well head cellar.

Original corrective action and date

Corrective Action: **Install BMPs to prevent wildlife access to cellar.**

Date: 06/13/2020

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	

Comment: Inspection #696201325 observed that the cellar at well #051-06129 has filled with fluid/chemicals, and required Operator to remove chemicals from within containment.
 It was observed in this inspection that chemicals have been removed per the corrective action.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402480032	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5237082
696201676	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5237075