

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Vertical Separator

1

Comment:

Corrective Action:

Date:

Type: Bradenhead

1

Comment: is plumbed to surface

Corrective Action:

Date:

Type: Progressive Cavity

1

Comment:

Corrective Action:

Date:

Type: Prime Mover

1

Comment:

Corrective Action:

Date:

Type: Deadman # & Marked

4

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment: CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	STEEL AST		37.144722,-104.913596
Comment: <input type="text"/>					
Corrective Action: <input type="text"/>					Date: <input type="text"/>

Paint

Condition: Adequate

Other (Content)

Other (Capacity) 30bbl	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date: <input style="width: 100px;" type="text"/>

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date: <input style="width: 100px;" type="text"/>

Flaring:

Type			
Comment:			
Corrective Action:			Date: <input style="width: 100px;" type="text"/>

Inspected Facilities

Facility ID: 288298 Type: WELL API Number: 071-09112 Status: PR Insp. Status: PR

Producing Well

Comment:		
Corrective Action:		Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695103295	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5250926