

Inspection Photos

API: 071-06721

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 9/16/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06721 | Date: 9/16/2020

Inspection Photos



Photo 1. Facing southeast toward the access road which has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06721 | Date: 9/16/2020

Inspection Photos



Photo 2. Facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06721 | Date: 9/16/2020

Inspection Photos



Photo 3. The pit remains at the location and has not been backfilled and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06721 | Date: 9/16/2020

Inspection Photos



Photo 4. There is erosion along the cut slope of the pit which is not stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06721 | Date: 9/16/2020

Inspection Photos



Photo 5. Facing northwest toward the pit location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06721 | Date: 9/16/2020

Inspection Photos



Photo 6. Facing north towards the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06721 | Date: 9/16/2020