

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/17/2020

Submitted Date:

09/18/2020

Document Number:

700403479

FIELD INSPECTION FORM
 Loc ID: 315204 Inspector Name: Moran, Rick On-Site Inspection: ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 3975

Name of Operator: ARGALI EXPLORATION COMPANY

Address: PO BOX 416

City: RANGELY State: CO Zip: 81648

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, Argali Exploration Company	970-629-1906	argaliexplorationcompany@gmail.com	
Thompson, Bud		BLThomps@BLM.gov	
Heil, John		john.heil@state.co.us	
Rector, Jeff		jbrduco@yahoo.com	
Rector, Jeff		jbrduco@yahoo.com	
Blyster, Brandon		blysteroil@aol.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230410	WELL	PR	09/18/1977	GW	103-08073	FEDERAL 1-29	PR

General Comment:

A follow up inspection of FIR documents:

1) 700401221 dated 4-24-2020.

2) 700401914 dated 6-9-2020.

The following compliance issues are uncompleted:

1) Meter building pit filled with sediment. Submit eForm 27 for pit closure. Photos 1, 4, 5, 6. Complete by 5-24-2020.

This is a summary of inspection report 700403479.

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PIT		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	230410	Type:	WELL	API Number:	103-08073	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Fail					

Comment: Stormwater sediment from slope has filled in pit.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Type: <u>Blowdown</u>	Lined:	Pit ID:	Lat:	Long:
-----------------------	--------	---------	------	-------

Reference Point: _____	Other: _____	Length: _____	Width: _____
------------------------	--------------	---------------	--------------

Lining:

Liner Type: _____ Liner Condition: _____

Comment: Well head pit.

Corrective

Date: _____

Fencing:

Fencing Type: Wildlife

Fencing Condition: Adequate

Comment: _____

Corrective

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Corrective

Date: _____

Anchor Trench Present:

Oil Accumulation: NO

2+ feet Freeboard: YES

Comment: _____

Corrective

Date: _____

Type: <u>Blowdown</u>	Lined:	Pit ID:	Lat:	Long:
-----------------------	--------	---------	------	-------

Reference Point: _____	Other: _____	Length: _____	Width: _____
------------------------	--------------	---------------	--------------

Lining:

Liner Type: _____ Liner Condition: _____

Comment: Meter building pit.

Corrective

Date: _____

Fencing:

Fencing Type: Wildlife

Fencing Condition: Adequate

Comment: _____

Corrective

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Corrective

Date: _____

Anchor Trench Present:

Oil Accumulation: NO2+ feet Freeboard: NO

Comment:

The pit is filled with stormwater sediment runoff from the adjacent slope and no berm is present.

Submit a Form 27 demonstrating that the pit was closed per COGCC 900 series rules. Contact the West Environmental Protection Specialist (John Heil, john.heil@state.co.us) for guidance.

Corrective

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700403480	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5251180