

**Inspection Photos**  
**Operator: BP America**  
**API: 067-08897**  
**Date: 9/18/2020**



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Revegetation is progressing with grasses such as western wheatgrass and smooth brome.



Photo 3. View of the eastern project area from the northeastern corner facing southward. Musk thistles appear herbicide-treated. Monitoring and treatment needs to continue as seedheads appear to support viable seed material.



Photo 4. View of reference area vegetation comprised of ponderosa pine woodland with understory of gambel oak, western wheatgrass, and antelope bitterbrush.



Photos 5/6. Locked gate coming in (left) and leaving (right).