

Inspection Photos
Operator: BP America
API: 067-08882
Date: 9/18/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the eastern fill slope from the southeastern corner facing northward. Revegetation is progressing with grasses such as western wheatgrass and sand dropseed, largely in a grazed condition.



Photo 3. View of the southern fill slope from the southeastern corner facing eastward.



Photo 4. View of reference area vegetation comprised of ponderosa pine woodland with understory of gambel oak, western wheatgrass, and antelope bitterbrush.



Photos 5/6. Locked gate coming in (left) and leaving (right).