

Inspection Photos  
Operator: BP America  
API: 067-08881  
Date: 9/18/2020



Photo 1. View of the project area from the northeastern corner facing center.





Photo 2. View of the northern fill slope from the northeastern corner facing westward. Revegetation is progressing with grasses such as western wheatgrass and sand dropseed, largely in a grazed condition.





Photo 3. View of the western fill slope from the northwestern corner facing southward.





Photo 4. View of reference area vegetation comprised of ponderosa pine woodland with understory of gambel oak, western wheatgrass, and antelope bitterbrush.





Photos 5/6. Locked gate coming in (left) and leaving (right).