

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/13/2020

Submitted Date:

09/14/2020

Document Number:

693503477

FIELD INSPECTION FORM

 Loc ID 307376 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 10672
 Name of Operator: TIMBER CREEK OPERATING LLC
 Address: 6295 GREENWOOD PLAZA BLVD #100
 City: GREENWOOD State: CO Zip: 8111-
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 11 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Santistevan, Vince	719-845-2102/719-680-9705	vincasantistevan@tcenergyllc.com	All Inspections
Beardslee, Tom		tom.beardslee@state.co.us	
Mack, Ronald		ronaldmack@tcenergyllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217563	WELL	TA	06/20/2016	GW	071-06340	APACHE CANYON 17-13	TA

General Comment:

Location

Lease Road:			
Type	Main		
comment:	Lease road between AC 17-14 and AC 17-13 Does not appear to properly maintained ruts and sediment build up in bar ditch is causing BMP's to fail .		
Corrective Action	Comply rule 1002f	Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	_____

Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds on location		
Corrective Action:	Comply with rule 603f	Date:	
Type	UNUSED EQUIPMENT		
Comment:	Flow line risers not LO/TO or marked are considered unused equipment.		
Corrective Action:	Comply with Rule 603.f . for unused, unmarked flow line risers 24 hrs. to lock out tag out. 30 days to remove riser.	Date:	
Type	UNUSED EQUIPMENT		
Comment:	Well has been TA for a extended period of time equipment is considered unused equipment.		
Corrective Action:	Comply with rule 603f	Date:	
Type	TRASH		
Comment:	Pipeline marker		
Corrective Action:	Comply with rule 603 f	Date:	

Overall Good:

Spills:			
Type	Area	Volume	
In Containment:	No		
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type			
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panel		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 217563 Type: WELL API Number: 071-06340 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Sunday September 13, 2020 at approximately 1:56PM, I, Inspector Randy Silver, conducted an on-site inspection. Location: AC 17-13 Operator: Timber Creek API#:05-071-06340 County: Las Animas While there, I observed lease road and well site During this inspection the following possible compliance issues were observed: Storm water main lease road: Rule 1002 f Corrective action date of 10-13-20 Weeds: Rule 603 f See photo 2 LOTO: Rule 603f See photos 2,3 Unused equipment: Rule 603 f Well has been TA for a extended period of time please provide future plans for utilization per rule 319 b (3) This inspection is being entered for notification and documentation only and is not intended to provide the Operator the opportunity to resolve the alleged violations without the imposition of a penalty, pursuant to Rule 522.c.</p> <p>Weather conditions: Clear and dry A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	09/13/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402489925	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5248097
693503478	lov pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5248091