

**Inspection Photos**  
**Operator: BP America**  
**API: 067-06948**  
**Date: 9/18/2020**



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern fill slope from the northwestern corner facing eastward. Revegetation is progressing with grasses such as western wheatgrass and sand dropseed, largely in a grazed condition. Musk thistles appear to be herbicide treated in a post-flowering condition.



Photo 3. View of reference area vegetation comprised of ponderosa pine woodland with understory of gambel oak, western wheatgrass, squirreltail, and antelope bitterbrush.



Photos 4/5. Locked gate coming in (left) and leaving (right).