

Inspection Photos
Operator: BP America
API: 067-06778
Date: 9/18/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of bare soils on the southwestern cut-slope where stabilization is needed.



Photo 3. View of the northern fill slope from the northeastern corner facing westward. Revegetation is progressing with grasses such as western wheatgrass, largely in a grazed condition.



Photo 4. View of the eastern fill slope facing southward. Shallow berm and cobble BMPs are placed and appear to be functioning at this time.



Photo 5. View of reference area vegetation comprised of ponderosa pine woodland with understory of gambel oak, western wheatgrass, squirreltail, and antelope bitterbrush.



Photos 6/7. Locked gate coming in (left) and leaving (right).