

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/08/2020

Submitted Date:

09/16/2020

Document Number:

688308512

FIELD INSPECTION FORM

Loc ID: 316997 Inspector Name: Sherman, Susan On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10691
Name of Operator: PHOENIX RESOURCES LLC
Address: 5566 S SYCAMORE STREET
City: LITTLETON State: CO Zip: 80120

Findings:

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Heffner, Taylor	303-219-3362	theffner@phxresources.com	
Wolfe, Stephen		stephen.wolfe@state.co.us	COGCC Engineer

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
234270	WELL	SI	10/01/2018	OW	121-06377	BLAKE 1	TA

General Comment:

MIT Inspection, FAILED
Form 42 Notice 402478153

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		
Crude Oil	WELLHEAD	<= 1 bbl		
Comment: Crude oil at wellhead spilled while pressuring well up, ~10 gals. Was contained in dirt berm right away.				
Corrective Action: Properly dispose of stained soil			Date:	09/16/2020

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 234270 Type: WELL API Number: 121-06377 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: MIT, FAILED, hole failed to load or hold to pressure, pressured up to 370 psi but went to below 300 psi in a minute, bradenhead leaking oil

Corrective Action: **Repair (retest) or plug and abandon.** Date: 12/08/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402490644	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5248908
688308519	Phoenix Resources Blake 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5248902
688308533	Form 21 Failed	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5248903