

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/16/2020

Submitted Date:

09/16/2020

Document Number:

699801794

**FIELD INSPECTION FORM**Loc ID 312498 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

3 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Graves, Jim		mrinc20@maralexinc.com	
Jordan, Reid		maralextechjr@gmail.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
, Engineering		dnr_cogccengineering@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221784	WELL	SI	01/08/1992	GW	077-08386	DOMA ALBERTSON 1-32	TA

**General Comment:****COGCC Inspection Report Summary**

On Wednesday 9/16/20 at approximately 14:00 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at MARALEX RESOURCES INC DOME ALBERTSON-69S98W /32SENW, Location #312498 in Mesa County Colorado.

Refer to document #699801006 inspection conducted on 4/29/20. Not all previous corrective actions have been completed.

During this inspection the following possible compliance issues were observed: Multiple places with debris on location. See photo #1090, #1893, #1091 and #1894 with a previous corrective action date of 5/13/20. MIT required on well. With a previous corrective action date of 7/29/20. No pit permit on record. With a previous corrective action date of 5/29/20.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.  
This is a summary of inspection report.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911			
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	DEBRIS			
Comment:	Multiple places with debris on location. See photo #1090, #1894 ,#1091 and #			
Corrective Action:	Production facilities, shall be kept free of weeds and rubbish. Remove all debris from location.			Date: 05/13/2020
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	PIT			
Comment:	Hog panels			
Corrective Action:				Date:
<b>Equipment:</b>				
				corrective date
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:				Date:
<b>Venting:</b>				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:



**Inspected Facilities**Facility ID: 221784 Type: WELL API Number: 077-08386 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Last produced prior to 1999. Last MIT preformed on 1/28/14.Corrective Action: A mechanical integrity test shall be performed on each shut-in well on 5 year intervals from the date the initial mechanical integrity test was performed. Preform MIT on well. Date: 07/29/2020

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PITType: BlowdownLined: NO

Pit ID: \_\_\_\_\_

Lat: \_\_\_\_\_

Long: \_\_\_\_\_

Reference Point: \_\_\_\_\_

Other: \_\_\_\_\_

Length: \_\_\_\_\_

Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_

Liner Condition: \_\_\_\_\_

Comment:

No pit permit on record.

Corrective Action

Submit an eForm 15 Pit Report to update COGCC records with current information.

Date:

05/29/2020**Fencing:**Fencing Type: LivestockFencing Condition: Adequate

Comment: \_\_\_\_\_

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_

Netting Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: NOOil Accumulation: NO2+ feet Freeboard: YES

Comment: \_\_\_\_\_

Corrective Action

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<u>All equipment has been removed from location. All that remains is the wellhead and pit.</u>	depaoloc	09/16/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
402491245	INSPECTION SUBMITTED	<a href="http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5249647">http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5249647</a>
699801795	Photos for Insp. #699801794	<a href="http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5249644">http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5249644</a>