

Inspection Photos
Operator: Enduring Resources
API: 067-07467
Date: 9/23/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern fill slope from the southeastern edge facing westward. Revegetation is progressing with grasses such as western wheatgrass, crested wheatgrass, and intermediate wheatgrass.



Photo 3. View of the northern project area the northeastern corner facing westward.



Photo 4. View of culvert outlet near the well pad entrance, appears to be stabilized at this time.



Photo 5. View of the reference area comprised of open pinyon and juniper woodland with black sage and grasses/forbs in the understory such as western wheatgrass, Indian ricegrass, and penstemon.