

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/22/2020

Submitted Date:

09/24/2020

Document Number:

696103767

FIELD INSPECTION FORM

Loc ID 423200 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

15 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
423185	WELL	TA	03/11/2020	OW	123-33520	HOWARD USX A 09-19	TA
423201	WELL	SI	11/01/2017	OW	123-33531	HOWARD USX A 09-12D	TA
423202	WELL	SI	03/01/2018	OW	123-33532	HOWARD USX A 09-06D	TA

General Comment:

This is a WELL inspection.
Well(s): 3: Temporarily Abandoned | TA.
Battery: Inactive | Shut-down.

Refer to Field Inspection Report doc. #696103629 and/or Location ID #423200 for Battery / Facility, Equipment info.

Follow-up to Field Inspection Report doc. #696103629 dated 08/28/2020.

Refer to Field Inspection Report Resolution Form doc. #402484623 dated 09/09/2020.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	3: wellsites.		
Corrective Action:		Date:	
Type			
Comment:	Refer to Field Inspection Report doc. #696103629 and/or Location ID #423200 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	<p>Prior insp: Weed encroachment at 3 wellsites. Howard USX A 09-19, Howard USX A 09-12D, Howard USX A 09-06D. Refer to Rule 603.f for guidance. Remove, manage, & control weeds around 3 wellsites. Howard USX A 09-19, Howard USX A 09-12D, Howard USX A 09-06D. Comply with Rule 603.f. Corrective Action date: 09/14/2020.</p> <p>This insp: * Weeds around 3 wellsites NOW appear mitigated. See photos #1-8.</p> <p>**Refer to Field Inspection Report Resolution Form doc. #402484623 dated 09/09/2020. This document states weeds have been removed on 09/09/2020. Todays inspection confirms that weeds mitigated on 3 wellsites.</p>		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	3: Wellsites. Iron panel.		

Corrective Action:		Date:	
Type			
Comment:	Refer to Field Inspection Report doc. #696103629 and/or Location ID #423200 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	

Equipment:

		corrective date
Type: Plunger Lift	# 3	
Comment:	3: wellsites.	
Corrective Action:		Date:
Type: Bradenhead	# 3	
Comment:	3: wellsites. Appears plumbed to surface.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			OTHER		40.504586,-104.563040
Comment:	Refer to Field Inspection Report doc. #696103629 and/or Location ID #423200 for Battery / Facility, Equipment info.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 423185 Type: WELL API Number: 123-33520 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
 Disconnected from flowline.
 COGCC records indicate last production: 02/2018.
 Blue TA tag for SI/TA status present at wellsite.
 Locked-Out, Tagged-Out | LOTO.

 Form 4 Sundry doc. #402339877 indicates TA status: 12/11/2019. Approved.
 Form 21-MIT doc. #402271258 indicates MIT done: 12/19/2019. Approved.
 Form 42 doc. #402235320 MIT 10-Day Notice: 11/20/2019. Approved.

Corrective Action: _____ Date: _____

Facility ID: 423201 Type: WELL API Number: 123-33531 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
 Disconnected from flowline.
 COGCC records indicate last production: 10/2017.
 Blue TA tag for SI/TA status present at wellsite.
 Locked-Out, Tagged-Out | LOTO.

 Form 21-MIT doc. #402271363 indicates MIT done: 12/18/2019. Approved.
 Form 42 doc. #402252718 MIT 10-Day Notice: 12/12/2019. Approved.

Corrective Action: _____ Date: _____

Facility ID: 423202 Type: WELL API Number: 123-33532 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
 Disconnected from flowline.
 COGCC records indicate last production: 02/2018.
 Blue TA tag for SI/TA status present at wellsite.
 Locked-Out, Tagged-Out | LOTO.

 Form 21-MIT doc. #402271348 indicates MIT done: 12/18/2019. Approved.
 Form 42 doc. #402252724 MIT 10-Day Notice: 12/12/2019. Approved.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On TUE 09/22/2020 at approximately 15:47 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: HOWARD USX A /09-19 Location ID: 423200 Well Names: Howard USX A 09-19, Howard USX A 09-12D, Howard USX A 09-06D API: 05-123-33520, 05-123-33531, 05-123-33532 Location County: Weld County, Colorado Weather: Partly cloudy, dry.</p> <p>While there, I observed: Well(s): 3: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Refer to Field Inspection Report doc. #696103629 and/or Location ID #423200 for Battery / Facility, Equipment info.</p> <p>Follow-up to Field Inspection Report doc. #696103629 dated 08/28/2020.</p> <p>Refer to Field Inspection Report Resolution Form doc. #402484623 dated 09/09/2020. This document states weeds have been removed on 09/09/2020. Today's inspection confirms that weeds mitigated on 3 wellsites.</p> <p>During this inspection, the following prior possible compliance issues appear to be addressed: 1.) Weed encroachment at 3 wellsites. Howard USX A 09-19, Howard USX A 09-12D, Howard USX A 09-06D. Refer to Rule 603.f for guidance. Remove, manage, & control weeds around 3 wellsites. Howard USX A 09-19, Howard USX A 09-12D, Howard USX A 09-06D. Comply with Rule 603.f. Corrective Action date: 09/14/2020. * Weeds around 3 wellsites NOW appear mitigated. See photos #1-8.</p> <p>During this inspection, NO New/Current possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	09/23/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696103768	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5254982