

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/22/2020

Submitted Date:

09/24/2020

Document Number:

696103769

**FIELD INSPECTION FORM**

Loc ID 306349 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1001 NOBLE ENERGY WAY  
City: HOUSTON State: TX Zip: 77070

**Findings:**

12 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288024	WELL	PR	04/01/2020	OW	123-24495	HOWARD USX A 9-10	PR

**General Comment:**

This is a WELL inspection.  
Well(s): 1: Producing | PR.  
Battery: Active.

Centralized Battery serves 3 Location IDs (423191, 306349, 306350).  
(Well(s): 5: Producing | PR ; 1: Plugged & Abandoned | PA).

Centralized Battery formerly served 1 Location ID (306347).  
(Well(s): 1: Plugged & Abandoned | PA).

Refer to Field Inspection Report doc. #696103640 and/or Location ID #423191 for Battery / Facility, Equipment info.

Follow-up to Field Inspection Report doc. #696103642 dated 09/01/2020.

Refer to Field Inspection Report Resolution Form doc. #402483908 dated 09/08/2020.

<b>Location</b>			
<b>Lease Road:</b>			
	Type Access		
	comment: Adequate		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
	Type		
	Comment: Refer to Field Inspection Report doc. #696103640 and/or Location ID #423191 for Battery / Facility, Equipment info.		
Corrective Action:			Date:
	Type WELLHEAD		
	Comment:		
Corrective Action:			Date:
<b>Emergency Contact Number:</b>			
	Comment:		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	<p>Prior insp: Weed encroachment at wellsite. Refer to Rule 603.f for guidance. Remove, manage, &amp; control weeds around wellsite. Comply with Rule 603.f. Corrective Action date: 09/16/2020.</p> <p>This insp: * Weeds around wellsite NOW appears mitigated. See photos #1, 2.</p> <p>**Refer to Field Inspection Report Resolution Form doc. #402483908 dated 09/08/2020. This document states weeds have been removed on 09/08/2020. Todays inspection confirms that weeds mitigated on wellsite.</p>		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
	Type		
Comment:	Refer to Field Inspection Report doc. #696103640 and/or Location ID #423191 for Battery / Facility, Equipment info.		

Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type:	#		
Comment:	Refer to Field Inspection Report doc. #696103640 and/or Location ID #423191 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.496656,-104.550730
Comment:	Centralized Battery serves 3 Location IDs (423191, 306349, 306350). (Well(s): 5: Producing   PR ; 1: Plugged & Abandoned   PA).  Centralized Battery formerly served 1 Location ID (306347). (Well(s): 1: Plugged & Abandoned   PA).  Refer to Field Inspection Report doc. #696103640 and/or Location ID #423191 for Battery / Facility, Equipment info.				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type	
------	--

Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 288024 Type: WELL API Number: 123-24495 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing | PR.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On TUE 09/22/2020 at approximately 15:11 hrs. I, Bret Evins, conducted an on-site inspection at:                      Operator Name: NOBLE ENERGY INC                      Location Name: HOWARD USX A-66N64W /9NWSE                      Location ID: 306349                      Well Name: Howard USX A 9-10                      API: 05-123-24495                      Location County: Weld County, Colorado                      Weather: Partly cloudy, dry.</p> <p>While there, I observed:                      Well(s): 1: Producing   PR.                      Battery: Active.</p> <p>Centralized Battery serves 3 Location IDs (423191, 306349, 306350).                      (Well(s): 5: Producing   PR ; 1: Plugged &amp; Abandoned   PA).</p> <p>Centralized Battery formerly served 1 Location ID (306347).                      (Well(s): 1: Plugged &amp; Abandoned   PA).</p> <p>Refer to Field Inspection Report doc. #696103640 and/or Location ID #423191 for Battery / Facility, Equipment info.</p> <p>Follow-up to Field Inspection Report doc. #696103642 dated 09/01/2020.</p> <p>Refer to Field Inspection Report Resolution Form doc. #402483908 dated 09/08/2020. This document states weeds have been removed on 09/08/2020. Today's inspection confirms that weeds mitigated on wellsite.</p> <p>During this inspection, the following prior possible compliance issues appear to be addressed:                      1.) Weed encroachment at wellsite.                      Refer to Rule 603.f for guidance.                      Remove, manage, &amp; control weeds around wellsite.                      Comply with Rule 603.f.                      Corrective Action date: 09/16/2020.                      * Weeds around wellsite NOW appears mitigated.                      See photos #1, 2.</p> <p>During this inspection, NO New/Current possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	<p>evinsb</p>	<p>09/24/2020</p>

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696103770	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5254983">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5254983</a>