

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/22/2020

Submitted Date:

09/24/2020

Document Number:

696103771

FIELD INSPECTION FORM

Loc ID 306350 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

12 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288023	WELL	PR	05/01/2019	OW	123-24496	HOWARD USX A 9-11	PR

General Comment:

This is a WELL inspection.
Well(s): 1: Producing | PR.
Battery: Active.

Centralized Battery serves 3 Location IDs (423191, 306349, 306350).
(Well(s): 5: Producing | PR ; 1: Plugged & Abandoned | PA).

Centralized Battery formerly served 1 Location ID (306347).
(Well(s): 1: Plugged & Abandoned | PA).

Refer to Field Inspection Report doc. #696103640 and/or Location ID #423191 for Battery / Facility, Equipment info.

Follow-up to Field Inspection Report doc. #696103644 dated 09/01/2020.

Refer to Field Inspection Report Resolution Form doc. #402483915 dated 09/08/2020.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type			
Comment:	Refer to Field Inspection Report doc. #696103640 and/or Location ID #423191 for Battery / Facility, Equipment info.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	<p>Prior insp: Weed encroachment at wellsite. Refer to Rule 603.f for guidance. Remove, manage, & control weeds around wellsite. Comply with Rule 603.f. Corrective Action date: 09/16/2020.</p> <p>This insp: * Weeds around wellsite NOW appears mitigated. See photos #1, 2.</p> <p>**Refer to Field Inspection Report Resolution Form doc. #402483915 dated 09/08/2020. This document states weeds have been removed on 09/08/2020. Today's inspection confirms that weeds mitigated on wellsite.</p>		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:
Type			
Comment:	Refer to Field Inspection Report doc. #696103640 and/or Location ID #423191 for Battery / Facility, Equipment info.		

Corrective Action:	Date:
--------------------	-------

Equipment:		corrective date
Type: Plunger Lift	# 1	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment: Appears plumbed to surface.		
Corrective Action:		Date:
Type:	#	
Comment: Refer to Field Inspection Report doc. #696103640 and/or Location ID #423191 for Battery / Facility, Equipment info.		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.496656,-104.550730
Comment: Centralized Battery serves 3 Location IDs (423191, 306349, 306350). (Well(s): 5: Producing PR ; 1: Plugged & Abandoned PA). Centralized Battery formerly served 1 Location ID (306347). (Well(s): 1: Plugged & Abandoned PA). Refer to Field Inspection Report doc. #696103640 and/or Location ID #423191 for Battery / Facility, Equipment info.					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	
Date:	

Inspected Facilities

Facility ID: 288023 Type: WELL API Number: 123-24496 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing | PR.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On TUE 09/22/2020 at approximately 15:23 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: HOWARD USX A-66N64W /9NESW Location ID: 306350 Well Name: Howard USX A 9-11 API: 05-123-24496 Location County: Weld County, Colorado Weather: Partly cloudy, dry.</p> <p>While there, I observed: Well(s): 1: Producing PR. Battery: Active.</p> <p>Centralized Battery serves 3 Location IDs (423191, 306349, 306350). (Well(s): 5: Producing PR ; 1: Plugged & Abandoned PA).</p> <p>Centralized Battery formerly served 1 Location ID (306347). (Well(s): 1: Plugged & Abandoned PA).</p> <p>Refer to Field Inspection Report doc. #696103640 and/or Location ID #423191 for Battery / Facility, Equipment info.</p> <p>Follow-up to Field Inspection Report doc. #696103644 dated 09/01/2020.</p> <p>Refer to Field Inspection Report Resolution Form doc. #402483915 dated 09/08/2020. This document states weeds have been removed on 09/08/2020. Today's inspection confirms that weeds mitigated on wellsite.</p> <p>During this inspection, the following prior possible compliance issues appear to be addressed: 1.) Weed encroachment at wellsite. Refer to Rule 603.f for guidance. Remove, manage, & control weeds around wellsite. Comply with Rule 603.f. Corrective Action date: 09/16/2020. * Weeds around wellsite NOW appears mitigated. See photos #1, 2.</p> <p>During this inspection, NO New/Current possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	<p>evinsb</p>	<p>09/24/2020</p>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696103772	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5254984