

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/17/2020

Submitted Date:

09/17/2020

Document Number:

699801800

FIELD INSPECTION FORM

Loc ID 312561 Inspector Name: De Paolo, Corey On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 53255
Name of Operator: MARALEX RESOURCES INC
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Jordan, Reid		maralextechjr@gmail.com	
Graves, Jim		mrinc20@maralexinc.com	
, BLM		jbyers@blm.gov	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221908	WELL	SI	07/09/1984	GW	077-08510	USA 1-9C	TA

General Comment:

[COGCC Inspection Report Summary](#)
On Thursday 9/17/20 at approximately 12:00 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at MARALEX RESOURCES INC DOME USA-610S98W /9SWNW, Location #312561 in Mesa County Colorado.
Refer to document #699801008 inspection conducted on 4/29/20. Not all corrective actions have been completed.

During this inspection the following possible compliance issues were observed: MIT required on well. With a previous corrective action date of 7/29/20.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report.

Location

Lease Road:

Type Access

comment:

Corrective ActionL

Date:

Overall Good:

Signs/Marker:

Type WELLHEAD

Comment:

Corrective Action:

Date:

Emergency Contact Number:

Comment: 970-563-4000

Corrective Action:

Date: _____

Good Housekeeping:

Type UNUSED EQUIPMENT

Comment:

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Deadman # & Marked # 4

Comment:

Corrective Action:

Date:

Type: Plunger Lift # 1

Comment:

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 221908 Type: WELL API Number: 077-08510 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well last produced prior to 1999. No MIT on record.

Corrective Action: All temporarily abandoned wells shall pass a mechanical integrity test. Preform MIT on well.

Date: 07/29/2020

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
All equipment has been removed from location. Only the wellhead remains.	depaoloc	09/17/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402492430	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5250634
699801801	Photos for Insp. #699801800	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5250631