

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/24/2020

Submitted Date:

09/25/2020

Document Number:

696103775

FIELD INSPECTION FORM

Loc ID 332473 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1775 SHERMAN STREET - STE 3000
City: DENVER State: CO Zip: 80203

Findings:

13 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273412	WELL	TA	08/05/2020	OW	123-22344	HOWARD LAKE 12-9	TA

General Comment:

This is a WELL inspection.
Well(s): 1: Temporarily Abandoned | TA.
Battery: Inactive | Shut-down.

Centralized Battery serves 2 Location IDs (332473, 305508).
(Well(s): 1: Temporarily Abandoned | TA ; 1: Shut-In | SI).

Centralized Battery formerly served 1 Location ID (305382).
(Well(s): 1: Plugged & Abandoned | PA).

Refer to Field Inspection Report doc. #696103633 and/or Location ID #332473 for Battery / Facility, Equipment info.

Follow-up to Field Inspection Report doc. #696103633 dated 08/28/2020.

Location			
Lease Road:			
	Type Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
	Type		
Comment:	Refer to Field Inspection Report doc. #696103633 and/or Location ID #332473 for Battery / Facility, Equipment info.		
Corrective Action:			Date:
	Type WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	<p>Prior insp: Weed encroachment at wellsite. Refer to Rule 603.f for guidance. Remove, manage, & control weeds around wellsite. Comply with Rule 603.f. Corrective Action date: 09/14/2020.</p> <p>This insp: * Weeds around wellsite NOW appears mitigated. See photos #1, 2.</p>		
Corrective Action:			Date:
Type	UNUSED EQUIPMENT		
Comment:	<p>Prior insp: Unused equipment at wellsite. (Wellhead fittings, wellhead, master valve on ground not attached to well). Refer to Rule 603.f for guidance. Remove unused equipment at wellsite. (Wellhead fittings, wellhead, master valve on ground not attached to well). Comply with Rule 603.f. Corrective Action date: 09/15/2020.</p> <p>This insp: * Unused equipment NOW installed and/or removed. See photos #1, 2.</p>		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:
Type			
Comment:	Refer to Field Inspection Report doc. #696103633 and/or Location ID #332473 for Battery / Facility, Equipment info.		
Corrective Action:			Date:

Equipment:

Type: Bradenhead	# 1		corrective date
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:
Type:	#		
Comment:	Refer to Field Inspection Report doc. #696103633 and/or Location ID #332473 for Battery / Facility, Equipment info.		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.504875,-104.563221
Comment:	Centralized Battery serves 2 Location IDs (332473, 305508). (Well(s): 1: Temporarily Abandoned TA ; 1: Shut-In SI). Centralized Battery formerly served 1 Location ID (305382). (Well(s): 1: Plugged & Abandoned PA). Refer to Field Inspection Report doc. #696103633 and/or Location ID #332473 for Battery / Facility, Equipment info.				
Corrective Action:					Date:

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	<input type="text"/>			
Corrective Action:				Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 273412 Type: WELL API Number: 123-22344 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Disconnected from flowline.
COGCC records indicate last production: 02/2020.

Form 5A doc. #402428377 indicates TA status: 03/12/2020. Approved.
Form 21-MIT doc. #402430739 indicates MIT done: 03/13/2020. Approved.
Form 42 doc. #402335429 MIT 10-Day Notice: 03/12/2020. Approved.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On THU 09/24/2020 at approximately 15:01 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: PDC ENERGY INC Location Name: HOWARD LAKE-66N64W /9SWNW Location ID: 332473 Well Name: Howard Lake 12-9 API: 05-123-22344 Location County: Weld County, Colorado Weather: Partly cloudy, dry.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 2 Location IDs (332473, 305508). (Well(s): 1: Temporarily Abandoned TA ; 1: Shut-In SI).</p> <p>Centralized Battery formerly served 1 Location ID (305382). (Well(s): 1: Plugged & Abandoned PA).</p> <p>Refer to Field Inspection Report doc. #696103633 and/or Location ID #332473 for Battery / Facility, Equipment info.</p> <p>Follow-up to Field Inspection Report doc. #696103633 dated 08/28/2020.</p> <p>During this inspection, the following prior possible compliance issues appear to be addressed: 1.) Weed encroachment at wellsite. Refer to Rule 603.f for guidance. Remove, manage, & control weeds around wellsite. Comply with Rule 603.f. Corrective Action date: 09/14/2020. * Weeds around wellsite NOW appears mitigated. See photos #1, 2.</p> <p>2.) Unused equipment at wellsite. (Wellhead fittings, wellhead, master valve on ground not attached to well). Refer to Rule 603.f for guidance. Remove unused equipment at wellsite. (Wellhead fittings, wellhead, master valve on ground not attached to well). Comply with Rule 603.f. Corrective Action date: 09/15/2020. * Unused equipment NOW installed and/or removed. See photos #1, 2.</p> <p>During this inspection, NO New/Current possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	<p>evinsb</p>	<p>09/25/2020</p>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696103776	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5256052