

Issue Report

Keller 20-13, 125-07340

Report created on September 22, 2020


Captured: September 2, 2020



Type	Count
Missing Part	1
Other	1

No.	Summary	Type	Created	Status
2	No access, seasonal inspection.	Missing Part	Sep 22, 2020 at 2:40pm	Open
1	Pumping unit fenced with steel panels in corn field.	Other	Sep 22, 2020 at 2:38pm	Open


Missing Part



No.	Summary	Created	Status
2	No access, seasonal inspection.	Sep 22, 2020 at 2:40 PM	Open

No. 2 OPEN**Captured:** Sep 2, 2020 at 12:02pm**Type**
Missing Part**Lat/Long**
39.88014, -102.48155**Summary**
No access, seasonal inspection.**Created**
Sep 22, 2020 at 2:40pm by Craig Quint

Other



No.	Summary	Created	Status
1	Pumping unit fenced with steel panels in corn field.	Sep 22, 2020 at 2:38 PM	Open

No. 1 OPEN*Captured: Sep 2, 2020 at 12:02pm***Type**
Other**Lat/Long**
39.88014, -102.48150**Summary**
Pumping unit fenced with steel panels in corn field.**Created**
Sep 22, 2020 at 2:38pm by Craig Quint