

Inspection Photos

API: 05-061-06480

Operator: MURFIN DRILLING COMPANY INC

Inspection Date: 9/24/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06480 | Date: 9/24/2020

Inspection Photos



Photo 1. Facing west toward the location. Vegetation is not establishing and there are areas bare of vegetation which indicate soil potential soil issues.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06480 | Date: 9/24/2020

Inspection Photos



Photo 2. Facing south toward the location.



Inspection Photos



Photo 3. Facing east at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06480 | Date: 9/24/2020

Inspection Photos



Photo 4. Facing south toward the surrounding undisturbed area which shows a uniform vegetation cover consisting of Blue grama, Sand dropseed, Prairie threeawn among other species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06480 | Date: 9/24/2020