

DC-3 Off-Location Flowline Right-of-Way(ROW) Photo Log



Photo 1: DC-3 ROW near DC-3 Location.



Photo2: DC-3 ROW looking south. Note the Gambel Oak establishing on the DC 3 ROW.



Photo 3: DC-3 ROW near Dolores CTY RD 15.



Photo 4: DC-3 ROW looking south. Note the Sage Brush establishing of the DC-3 ROW.