

Inspection Photos

API: 05-061-06713

Operator: THOMAS L SPRING LLC

Inspection Date: 9/24/2020



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06713 | Date: 9/24/2020

Inspection Photos



Photo 1. Facing north along the access road. The vehicle ruts needs to be graded out and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06713 | Date: 9/24/2020

Inspection Photos



Photo 2. Facing north toward the location. Equipment has not been removed and location is not reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06713 | Date: 9/24/2020

Inspection Photos



Photo 3. Facing east at the location. Equipment needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06713 | Date: 9/24/2020

Inspection Photos



Photo 4. There is oil in the tank which needs to be properly disposed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06713 | Date: 9/24/2020

Inspection Photos



Photo 5. Facing southwest at the location. The location needs to be decompacted and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06713 | Date: 9/24/2020

Inspection Photos



Photo 6. Facing north toward the surrounding undisturbed area which shows a uniform vegetation cover consisting of Blue grama, Sand dropseed, Prairie threeawn among other species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06713 | Date: 9/24/2020