

Inspection Photos

API: 05-011-06108

Operator: THOMAS L SPRING LLC

Inspection Date: 9/24/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-011-06108 | Date: 9/24/2020

Inspection Photos



Photo 1. Facing southwest at the location. There are pipe risers that have not been removed and are interfering with farming operations.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-011-06108 | Date: 9/24/2020

Inspection Photos



Photo 2. Facing northeast at the location. Abandoned risers need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-011-06108 | Date: 9/24/2020

Inspection Photos



Photo 3. Facing northwest at the location. The crop has not reestablished and needs to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-011-06108 | Date: 9/24/2020