

Inspection Photos

API: 05-011-06046

Operator: STRACHAN EXPLORATION INC

Inspection Date: 9/24/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-011-06046 | Date: 9/24/2020

Inspection Photos



Photo 1. Facing west along the access road. The access road has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-011-06046 | Date: 9/24/2020

Inspection Photos



Photo 2. Facing west toward the location. The location has not been reclaimed and soils are bare of vegetation. There is equipment that remains at the north side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-011-06046 | Date: 9/24/2020

Inspection Photos



Photo 3. There is pipe risers associated with the former well site that have not been removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-011-06046 | Date: 9/24/2020

Inspection Photos



Photo 4. Facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-011-06046 | Date: 9/24/2020

Inspection Photos



Photo 5. Facing north toward the location. The location has not been reclaimed and soils are bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-011-06046 | Date: 9/24/2020

Inspection Photos



Photo 6. Facing northwest toward the surrounding undisturbed area which shows a uniform vegetation cover consisting of Blue grama, Sand dropseed, Prairie threeawn among other species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-011-06046 | Date: 9/24/2020