



00272335

SUMMARY OF WORKOVER ON WEBSTER NO. 1

November 5, 1947: Killed well with 11# mud. Installed BOP. Pulled packer loose. Layed down tubing. Replaced leaking seal ring in casing head. Tested casing with 1200#. Tested OK.

Landed 13 joints of 2 7/8" tubing and 245 joints of 4 1/2" tubing at 5383' from PDF with Lane Wells Production Type Packer set at 5042' and Bowen safety joint at 5010'.

Pressured up on packer to 1200#, dropped very slowly to 1100#, indicating same casing condition as after the last workover.

Christmas Tree as Follows:

Tubing head adaptor	Macaloy (stainless steel)
Master Valve	McEvoy Macaloy
Tee	Macaloy (stainless steel)
Top Valve	WKM
Wing Valve	WKM (hastelloy coated)
Above top valve	Unibolt w/blanking plug
	Short lubricator
Gauges	At tubing, casing & surface
Wing Tee	Unibolt