

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/30/2020

Submitted Date:

09/30/2020

Document Number:

679603359

FIELD INSPECTION FORM

Loc ID 306589 Inspector Name: Santistevan, Brittani On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
6 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 69175
 Name of Operator: PDC ENERGY INC
 Address: 1775 SHERMAN STREET - STE 3000
 City: DENVER State: CO Zip: 80203

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289922	WELL	PR	03/06/2008	GW	123-24957	HEINRICY 11-7U	PR

General Comment:

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil under master valve. See attached photo.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f.(2).d.		Date: <u>10/30/2020</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:			Date:
Equipment:			
			corrective date
Type: Plunger Lift	# 1		
Comment:	<input type="text"/>		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	<input type="text"/>		
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:	<input type="text"/>		
Corrective Action:			Date:
Flaring:			
Type	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 289922 Type: WELL API Number: 123-24957 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>This is a follow up inspection to previous inspection DOC#: 679603119. All previous corrective actions have been resolved. One new corrective actions was observed at the time of re-inspection.</p> <p>COGCC Inspection Report Summary **Weather Conditions: sunny, dry ground On Wednesday, September 30, 2020 at approximately 11:15, I, Inspector Brittani Santistevan, conducted an on-site inspection at HEINRICY 11-7U (PDC Energy), at API #: 05-123-24957 in WELD COUNTY Colorado. While there, I observed a producing wellhead. During this inspection the following possible compliance issues were observed: 1. It appears that previous stained soil was removed, but it has re-accumulated again under the master valve of the wellhead. Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f.(2).d. (Corrective Action Date: October 30, 2020) See attached photo #3.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	09/30/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679603360	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5259996