

KP Kauffman - COGCC Inspection Photos
Location: UPPR 43 PAN AM G Consolidation #2 OLF Release
Spill ID # 478086 Date 9/28/2020



View of area of release and excavation activity on the north side of WCR 4; view north.



View of flowline exposed in excavation and pooled hydrocarbons; looking south.

KP Kauffman - COGCC Inspection Photos
Location: UPPR 43 PAN AM G Consolidation #2 OLF Release
Spill ID # 478086 Date 9/28/2020



**View of second excavation on the south side of WCR 4;
looking south.**



Close up view of flowline exposed in south excavation

KP Kauffman - COGCC Inspection Photos
Location: UPPR 43 PAN AM G Consolidation #2 OLF Release
Spill ID # 478086 Date 9/28/2020



View of valve and bullplug installed at north excavation.



**View of valve and bullplug installed at south excavation;
Historically abandoned flowline also present in excavation.**

KP Kauffman - COGCC Inspection Photos
Location: UPPR 43 PAN AM G Consolidation #2 OLF Release
Spill ID # 478086 Date 9/28/2020



View of replacement section of flowline (new HDPE) that has been pulled under WCR 4 through casing pipe from south to north excavations.



View from south excavation across WCR 4; looking north Replacement section of flowline being installed.