

Inspection Photos
Operator: BP America
API: 067-07431
Date: 9/29/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing, largely with western wheatgrass and crested wheatgrass. Musk thistle appear to be treated in a post-flowering condition with mature seedheads.



Photo 3. View of the western project area from the southwestern corner facing northward.



Photo 4. View of the reference area comprised of pinyon and juniper woodland with understory of black sagebrush, western wheatgrass, and gambel oak.