



**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	well is in middle of an alfalfa field		
Corrective Action:		Date:	

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	due to well being in an alfalfa field weeds have overgrown and need to be addressed now that there is access		
Corrective Action:		Date:	

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 95%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Ag fence		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	barbless wire		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	barbless wire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:	card in meter house indicates that calibration is not current		
Corrective Action:	comply with Rules 328/329 measurement of oil and gas.		Date: 12/30/2020
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 4		
Comment:	automation		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	appears to be plumbed to surface		
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	BV CONCRETE		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	60 bbl
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	shares containment with crude tanks			
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:					Date:	
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:					Date:	

**Inspected Facilities**Facility ID: 417934 Type: WELL API Number: 123-31791 Status: PR Insp. Status: PR**Producing Well**Comment: PR, Form 04 other Doc # 402374363 submitted on 4-17-2020 and is in process and From 42 (PR) Doc # 402436681 was submitted on 7-2-2020 and i approved.

Corrective Action:

Date:

**COGCC Comments**

Comment

User

Date

COGCC Inspection Report Summary  
 On Wednesday 9/30/2020 at approximately 1420 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Kerr McGee location:

Dechant X08-09 at API #05-123-31791 in Weld County Colorado.

While there, I observed a wellsite and tank battery. PR, Form 04 other Doc # 402374363 submitted on 4-17-2020 and is in process and From 42 (PR) Doc # 402436681 was submitted on 7-2-2020 and is approved.

During this inspection the following possible compliance issue was observed: 328/329 measurement of oil/gas. Card in meter house indicates that calibration is not current. CA date 12-30-2020 see photos 7 & 8.

Due to well being in an alfalfa field weeds have overgrown and need to be addressed now that there is access  
 See attached photos.  
 Location is dry, weather is clear.  
 A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.  
 This is a summary of inspection report.

revasr

09/30/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699302720	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5260121">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5260121</a>