

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/24/2020

Submitted Date:

09/24/2020

Document Number:

699102470**FIELD INSPECTION FORM**Loc ID 438202 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

18 Number of Comments

7 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	<a href="#">All Inspections</a>
Evins, Bret		bret.evins@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
438198	WELL	PR	01/06/2015	OW	123-39902	North Platte 11-41-33HNB	PR
438199	WELL	PR	12/26/2014	OW	123-39903	North Platte A-U-33HNB	PR
438200	WELL	PR	12/01/2018	OW	123-39904	North Platte A-U-33HC	PR
438201	WELL	PR	12/30/2014	OW	123-39905	North Platte A11-U41-33HNC	PR
438202	LOCATION	AC			-	North Platte A-33 Pad	AC
438203	WELL	PR	12/27/2014	OW	123-39906	North Platte 11-41-33HC	PR
438204	WELL	PR	12/20/2014	OW	123-39907	North Platte B11-V41-33HNC	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Missing placards "NFPA & Contents" on two different containers. See attached photos.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	10/26/2020

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment in the same containment as the separators, needs to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 603.f.	Date:	10/26/2020
Type	OTHER		
Comment:	Master valve appears to be leaking on multiple wellheads. See attached photos		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	10/26/2020
Type	OTHER		
Comment:	Oily waste in a bucket next to the compressor and in a bucket next to the pits in the tank battery containment needs to be removed for good housekeeping. See attached photos		
Corrective Action:	"Properly dispose of oily waste in accordance with 907.e."	Date:	10/26/2020
Type	OTHER		
Comment:	Stained soil inside of tank berms, needs to be removed for good housekeeping. See attached photos.		
Corrective Action:	"Properly dispose of oily waste in accordance with 907.e."	Date:	10/26/2020
Type	OTHER		
Comment:	Oily waste around the compressor needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	"Properly dispose of oily waste in accordance with 907.e."	Date:	10/26/2020
Type	TRASH		
Comment:	Trash "Wood Pallet" & "hose" needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 603.f.	Date:	10/26/2020

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities						
Facility ID:	438198	Type:	WELL	API Number: 123-39902	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	PR					
Corrective Action:						Date:
Facility ID:	438199	Type:	WELL	API Number: 123-39903	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	PR					
Corrective Action:						Date:
Facility ID:	438200	Type:	WELL	API Number: 123-39904	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	PR					
Corrective Action:						Date:
Facility ID:	438201	Type:	WELL	API Number: 123-39905	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	PR					
Corrective Action:						Date:
Facility ID:	438202	Type:	LOCATION	API Number: -	Status: AC	Insp. Status: AC
<b>Producing Well</b>						
Comment:	AC					
Corrective Action:						Date:
Facility ID:	438203	Type:	WELL	API Number: 123-39906	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	PR					
Corrective Action:						Date:
Facility ID:	438204	Type:	WELL	API Number: 123-39907	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	PR					
Corrective Action:						Date:
<b>COGCC Comments</b>						

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 9/24/20 at approximately 1540hrs, I, Inspector Adam Burns, Conducted an on-site inspection at North Platte A-33 Pad of Bonanza Creek Energy, at Location ID # 438202in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Missing placards "NFPA &amp; Contents" on two different containers. Install sign to comply with Rule 210.d. With a corrective action date of 10/26/20.</p> <p>Trash "Wood Pallet" &amp; "hose" needs to be removed for good housekeeping. Comply with Rule 603.f. With a corrective action date of 10/26/20.</p> <p>Oily waste around the compressor needs to be removed for good housekeeping. "Properly dispose of oily waste in accordance with 907.e." With a corrective action date of 10/26/20.</p> <p>Oily waste in a bucket next to the compressor and in a bucket next to the pits in the tank battery containment needs to be removed for good housekeeping. "Properly dispose of oily waste in accordance with 907.e." With a corrective action date of 10/26/20.</p> <p>Stained soil inside of tank berms, needs to be removed for good housekeeping. "Properly dispose of oily waste in accordance with 907.e." With a corrective action date of 10/26/20.</p> <p>Master valve appears to be leaking on multiple wellheads. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. With a corrective action date of 10/26/20.</p> <p>Unused equipment in the same containment as the separators, needs to be removed for good housekeeping. Comply with Rule 603.f. With a corrective action date of 10/26/20.</p> <p>See attached photos.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	burnsa	09/24/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402497463	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5255397">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5255397</a>
699102471	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5255395">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5255395</a>