

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/30/2020

Submitted Date:

10/01/2020

Document Number:

696103789

**FIELD INSPECTION FORM**Loc ID 422852 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

14 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422833	WELL	SI	07/01/2020	OW	123-33405	DYER USX A 05-14	SI

**General Comment:**

This is a WELL / BATTERY inspection.

Well(s): 1: Shut-In | SI.

Battery: Inactive | Shut-down.

Follow-up to Field Inspection Report doc. #696103688 dated 09/05/2020.

**Location****Lease Road:**

Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	<p>Prior insp: No Battery sign with well name posted at battery site. Refer to Rule 210.b. Post Emergency number, Company, &amp; Well name at Battery Isite. Comply w/ Rule 210.b. Corrective Action date: 11/23/2020.</p> <p>This insp: * Battery sign NOW appears posted at Battery site. See photos #2, 3, 4.</p>		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Surrounded by earth berms.		
Corrective Action:		Date:	

**Equipment:**

Type: Emission Control Device	# 2		corrective date
-------------------------------	-----	--	-----------------

Comment:	ECD #1: Controls crude oil tanks VOCs. ECD #2: Controls separator VOCs. Pilots: OFF   Shut-down.				
Corrective Action:				Date:	
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:				Date:	
Type: Bradenhead	# 1				
Comment:	Appears plumbed to surface.				
Corrective Action:				Date:	
Type: Gas Meter Run	# 1				
Comment:	Calibration card indicates calibration within last year. Last calibration: 04/06/2020. Meter is inactive. Shows no production.				
Corrective Action:				Date:	
Type: Bird Protectors	# 4				
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment	# 2				
Comment:	ECD scrubbers.				
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 2				
Comment:					
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	53 Bbls.	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:	Shares berms w/ crude oil tank.				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.513200,-104.583160
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	Shares berms w/ produced H2O vault.			
Corrective Action:			Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	422833	Type:	WELL	API Number:	123-33405	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose:		<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder: PRODUCTION RECORDS			
Comment:		<div>Shut-In   SI. Locked-Out, Tagged-Out   LOTO. COGCC records indicate last production: 07/2020.</div>							
Corrective Action:							Date:		

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On WED 09/30/2020 at approximately 15:06 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: NOBLE ENERGY INC  Location Name: DYER USX A /05-14  Location ID: 422852  Well Name: Dyer USX A 05-14  API: 05-123-33405  Location County: Weld County, Colorado  Weather: Mostly clear, dry.</p> <p>While there, I observed:  Well(s): 1: Shut-In   SI.  Battery: Inactive   Shut-down.</p> <p>Follow-up to Field Inspection Report doc. #696103688 dated 09/05/2020.</p> <p>During this inspection, the following prior possible compliance issues appear to be addressed:  1.) No Battery sign with well name posted at battery site.  Refer to Rule 210.b.  Post Emergency number, Company, &amp; Well name at Battery Isite. Comply w/ Rule 210.b.  Corrective Action date: 11/23/2020.  * Battery sign NOW appears posted at Battery site.  See photos #2, 3, 4.</p> <p>During this inspection, NO New/Current possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	10/01/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696103790	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5261083">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5261083</a>