

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/24/2020

Submitted Date:

09/24/2020

Document Number:

701100436

FIELD INSPECTION FORM

Loc ID 335471 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

Findings:

- 8 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290376	WELL	PR	12/27/2007	GW	045-14094	AP 44-15-695	PR
290377	WELL	PR	12/21/2007	GW	045-14095	AP 543-15-695	PR
414579	PIT	AC	04/27/2011		-	AP 43-15-695	AC

General Comment:

This is a summary of inspection report performed by Mike Longworth at TEP ROCKY MOUNTAIN LLC, AP-66S95W 15SESE Location # 335471
 During this inspection the following possible compliance issues were observed:
 Gaps in fencing/netting around the pit in north west corner and along south east corner of pit.
 Repair fencing/netting
 CA Date 9/25/2020 (24hours)
 Oil accumulation in pit.
 Remove condensate.
 CA Date 9/25/2020 (24hours)
 Methanol tank label is illegible. Condensate tank capacities are illegible.
 CA Date 12/25/2020
 Fence around tank battery is down and damaged around south east corner.
 Repair and maintain fencing around tank battery.
 CA Date 10/25/2020
 I Mike Longworth left a voice mail message at approximately 1:15 pm on Brad Moss' cell phone to inform Terra of the pit findings and 24 hour corrective action time line.
 A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Methanol tank label is illegible. Condensate tank capacities are illegible.		
Corrective Action:	Install sign to comply with Rule 210.d.		Date: 12/25/2020
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	TRASH		
Comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PIT		
Comment:			
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Fence around tank battery is down and damaged around south east corner.		
Corrective Action:	Repair and maintain fencing around tank battery.		Date: 10/25/2020
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 290376 Type: WELL API Number: 045-14094 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 290377 Type: WELL API Number: 045-14095 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 414579 Type: PIT API Number: - Status: AC Insp. Status: AC

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
Compaction	Pass					
Gravel	Pass					
		Compaction	Pass			
				Material Handling And Spill Prevention	Pass	
		Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: _____ Lined: YES Pit ID: 414579 Lat: 39.520970 Long: -107.976300

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: Adequate

Comment:

Corrective Action

Date: _____

Fencing:

Fencing Type: Netting/Fence com Fencing Condition: Adequate

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: Fence/Net Combo Netting Condition: Gaps

Comment: Gaps in fencing/netting around the pit in north west corner and along south east corner of pit.

Corrective Action Repair fencing/netting

Date: 09/25/2020

Anchor Trench Present: _____ Oil Accumulation: YES 2+ feet Freeboard: YES

Comment: Oil accumulation in pit.

Corrective Action Remove condensate.

Date: 09/25/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402497506	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5255478
701100437	Inspection 701100436 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5255474