

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Gas Meter Run

0

corrective date

Comment: **GAS METER HAS BEEN REMOVED**

Corrective Action:

Date: _____

Type: Bradenhead

0

Comment: **NO BRADENHEAD ON WELLHEAD ASSEMBLY.**

Corrective Action:

Date: _____

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	<50 BBLs	STEEL AST		,

Comment: **FLOWBACK TANK**

Corrective Action:

Date: _____

Paint

Condition:

Other (Content):

Other (Capacity): 30 BBL

Other (Type):

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:

Corrective Action:

Date: _____

Venting:

Yes/No NO

Comment:

Corrective Action:

Date: _____

Flaring:

Type:

Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 217443 Type: WELL API Number: 071-06220 Status: TA Insp. Status: PA**Idle Well**Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: THIS IS A P/A. OPERATOR TIH WITH TBG AND TAGGED CIBP @ 1120', (TOP PERFS ARE AT 1160', PUMPED 30 SKS NEET C CEMENT, POOK TO 302' AND PUMPED 10 SKS. WELL CIRCULATED WATER THE ENTIRE PUMP JOB. DID NOT GET CEMENT TO SURFACE. JUDGING FROM THE CEMENT ON THE TBG AFTER POOH TOP OF CEMENT ESTIMATED AT 60'. WOC TILL NEXT MORNING 10/2/20.

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
PER COGCC RULE OPERATOR HAS 90 DAYS FROM COMPLETION OF P/A PLUGGING TO SET WELL MARKER PLATE, REMOVE ALL EQUIPMENT, P/A ALL FLOWLINES AND RISERS AND START RECLAMATION PROCESS.	beardsit	10/02/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695103366	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5261392