

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /14NENE

Location ID: 324270



Photo #1974 from entrance to location.



Photo #1119 from inspection #699801046 conducted on 5/5/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /14NENE

Location ID: 324270



Photo #1976 Tank label weathered and not legible.



Photo #1978 Multiple places with debris and weeds on location.

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /14NENE

Location ID: 324270



Photo #1979 Multiple places with debris and weeds on location.



Photo 31977 Secondary containment not adequate weeds growing inside tank containment.